

Depden Parish Council Footpath Report January









Footpath 1: (A143 through to Depden Green)

This path starts from the A143 over a footbridge onto a concrete roadway followed by a Grassy track towards the Village Green. This is all clear until you try to cross over from the concrete road to the field, this short section is overgrown with grass and nettles which also obstructs the signage but is now passable due to winter die back of plants









Footpath 2: (Footpath from old A143 road up to the Church)

This Footpath starts from the old A143 road and ends up at the church. This Footpath to the church is all clear, well maintained with no issues, although muddy in places due to recent weather









Footpath 3: (From A143 road behind Rookery Farm, across a field Joining Footpath 1 at Depden Hall)

This footpath is in good condition across open meadows and farmland. After crossing the ditch, the Footpath is not clearly defined as the Headland is overgrown, the path across the field is also not clearly defined although it is all clear.









Footpath 4: (From near the Church, across the field joining Footpath 1 at Depden Hall)

A short stretch of footpath from near the church heading towards the Village Green via Footpath 1. the Footpath is not clearly defined as the Headland is overgrown and the path across the field is also not clearly defined although it is all clear.









Footpath 5: (From Beech Hall behind Highweek joining Footpath 3)

Starting from the old A143 near to Beech Hall passing behind the Garden centre and joining footpath 3 This footpath is in good condition, well maintained and clearly signposted.









(Peter Ebbens (06/01/2024)